

Cromemco Software Update Service Note Cromix-3

Date: October 8, 1981

Product: CROMIX-L and CROMIX-S

Version.release: 11.03 and 11.05

Date production of this version began: September 22, 1981 8"
September 22, 1981 5"

First serial number with this version: CX1611698 on 8" disks
CX1710938 on 5" disks

[Note: Earlier serial numbers may also contain this version. All Cromemco Finished Goods stock was recopied on the above dates.]

Description of enhancements, corrections, and known problems:

Version 11.05 of the Cromix Operating System is now available and contains one known problem. Refer to the Cromix Manual, part number 023-4022 and the Cromix-2 Software Update Service Note for more information on the operation of the Cromix Operating System.

Known Problem

Terminals using 16FDC or TU-ART ports will not currently run faster than 9600 baud. Terminals running on QUADART ports will run at 19,200 baud.

Corrections to the Cromix Operating System Manual

The blink description on page 71, paragraph 5, of the Cromix Instruction Manual, August 1981 is incorrect. The -s option must precede the filename of a library to be searched.